


Assembly Instruction

Article No: WH010978

STALBO

Screws :


- | | | | |
|---|------------------|--|------------------|
| (A)  | Ø3.0*16 18+1 Pcs | (B)  | Ø3.5*45 12+1 Pcs |
| (C)  | M6*40 4+1 Pcs | (D)  | Ø3.5*25 4+1Pcs |
| (E)  | Ø3.5*35 8+1 Pcs | | |

1




1 Pc

2




1 Pc

3




1 Pc

4




1 Pc

5



2 Pcs

6




1 Pc

7




1 Pc

8




1 Pc

9



1 Pc

10



1 Pc

11




2 Pcs

12



2 Pcs

13




1 Pc

14



1 Pc

15




2 Pcs

Assembly Instruction

Article No: WH010978


STALBO

STEP 1




(A)  Ø3.0*16 12Pcs

STEP 2




(B)  Ø3.5*45 4Pcs

STEP 3





(B)  Ø3.5*45 8Pcs

STEP 4



(C)  M6*40 4Pcs

STEP 5



(A)  Ø3.0*16 6Pcs

(D)  Ø3.5*25 4Pcs

(E)  Ø3.5*35 8Pcs